

---

**User's  
Manual**

2755

Portable Wheatstone Bridge

With Murray and Varley Loop Tester

---

## Cautionary Notes for Safe Use of the Product

- The following symbol is indicated on the instrument to ensure safe use.



"Handle with care!" This symbol is indicated where the operator must refer to instructions in the manual or attached material in order to protect personnel and the instrument.

- Since mishandling the instrument can result in an accident that may lead to injury or death of the operator, such as an electric shock, be sure to observe the following instructions.



### WARNING

- Protective Measures
  - If a crack appears in the instrument after it has been accidentally dropped or bumped, the safety-purpose insulation may be damaged. By all means do not use the instrument, but ask the manufacturer for repair.
- Connection
  - To avoid electric shock, be sure to apply protective grounding to the grounding terminal.
- Measurement
  - Always maintain the instrument within the limits for allowable current, voltage and power, during operation. If there is more than one limit for any of these parameters, the lowest limit takes precedence.
- External Power Supply
  - Only operate the instrument on a supply voltage no greater than 70 V DC.
- Operating Environment
  - Do not operate the instrument in a flammable or explosive gas atmosphere.
  - Do not operate the instrument if there is any condensation on it.
- Disassembly
  - Nobody except members of the manufacturer's service staff is allowed to disassemble the instrument.

- Since mishandling the instrument can result in an accident, such as an electric shock, that may injure the operator or damage the instrument, be sure to observe the following instructions.



### CAUTION

- Batteries
  - Do not use a mixture of different types of batteries or a mixture of old and new batteries. If the instrument will not be used for a prolonged period, remove the batteries before storage. The battery fluid will leak more readily during long-term storage, resulting in an instrument malfunction.
- Plastic Case
  - The panel and case of this instrument are made of ABS resin. Special caution must be taken to protect them from heat and organic solvent such as lacquer thinner.

### Notice regarding This User's Manual

1. The information covered in this user's manual is subject to change without prior notice.
2. Every effort has been made to ensure accuracy in the preparation of this manual. Should any errors or omissions come to your attention however, please inform Yokogawa Corporation accordingly.
3. Yokogawa Corporation is by no means liable for any damage resulting from the user's mishandling of the product.

## Precautions for Use



### WARNING

- External Power Supply

When external power supply is employed to increase sensitivity, full caution must be taken to avoid excess current flow, since all wire-wound bridge elements used in this instrument can endure up to 1 watt max. Before higher voltage is applied, take rough balance of bridge with low voltage. Caution must be taken not to set  $\times 1000$  dial to "0" and not to short-circuit Rx terminals.



### CAUTION

- Operation of Button Switch

- BA and GA button switches should be at OFF position after measurement.
- During measurement, BA button switch must be pressed prior to GA button switch. If this order is inverted, the movement of the galvanometer will be kicked when BA button switch is pushed due to inverse emf of inductance of the object under test, and the direction of measuring dial adjustment shall be thereby misled.

- Lead Resistance

In measurement of resistances below 10 ohms, the lead wire resistance should not be neglected. The lead resistance compensation must be made by measuring the lead resistance separately.

## CONTENTS

	Page
1. GENERAL .....	1
2. SPECIFICATIONS .....	1
3. CONSTRUCTION .....	3
3.1 Front Panel .....	3
3.2 External Galvanometer .....	4
3.3 External Power Supply .....	4
3.4 Cell Replacement .....	5
4. OPERATION .....	6
4.1 Preparation .....	6
4.2 Resistance Measurement .....	6
4.3 To find out approximate value of Rx .....	7
4.4 Interpolation .....	8
4.5 Murray Loop Test .....	8
4.6 Varley Loop Test .....	9
5. PRINCIPLES OF OPERATION .....	10
6. MAINTENANCE .....	11
COMPONENT LOCATION DIAGRAM .....	11
PART LIST .....	12
CIRCUIT DIAGRAM .....	13

## 1. GENERAL

The 2755 Portable Wheatstone Bridge is quite convenient with general resistance measurement and fault point detection of lines by Murray and Varley loop testing methods.

## 2. SPECIFICATIONS

Measuring Range:	1Ω to 10MΩ (4 digits)
Measuring arm:	1Ω×10+10Ω×10+ 100Ω×10 + 1000Ω×10 (4 dials)
Ratio arm:	×0.001, ×0.01, ×0.1, ×1, ×10, ×100, ×1000 and for Murray loop test M10, M100, M1000
Accuracy	
Overall	
100Ω to 100kΩ:	±0.1% of reading
10Ω to 1MΩ:	±0.3% of reading
1Ω to 10MΩ:	±0.6% of reading

### Measuring arm

×1000:	±0.06%
×100:	±0.1%
×10:	±0.5%
×1:	±3% (Including residual resistance)

### Multiply dial (Ratio)

×0.1, ×1, ×10:	±0.07%
×100, ×0.01:	±0.2%
×1000, ×0.001:	±0.5%
M10, M100, M1000:	±0.1%

### Temperature Coefficient of Resistance Elements

less than	±5×10 <sup>-5</sup> /°C (5 to 35°C)
	±2×10 <sup>-5</sup> /°C (20 to 35°C)

### Galvanometer

Sensitivity:	0.9μA/div. (±20%)
Internal resistance:	150Ω (±20%)
Period:	Within 2.6 seconds

Operating Temperature: 5 to 35°C

Operating Humidity: 85% R.H. or less

Power Source: Three 1.5V batteries (built-in) type SUM-1

Dimensions: Approx. 182×226×128mm

Weight : Approx. 2kg (4.4lbs)

#### Accessory

User's manual: 1 copy.

Carrying case (B9350AW): 1pc.

#### Optional Accessory

Carrying case: B9350AW (275600)

#### (Note)

\* For the measurement of more than 100kΩ, it is recommended to use external galvanometer, which has high sensitivity.

For example, the 2707 Electronic Galvanometer (Portable type 10μV/div. sensitivity) is suitable for above requirement. It is possible to measure 0.1% variation of Rx value of 2MΩ (4.5V power supply).

### 3. CONSTRUCTION

#### 3.1 Front Panel






Fig 3.1 Panel



**Fig 3.2 Connection of External Galvanometer**



**Fig 3.3 Connection of External Battery**

### 3.2 External Galvanometer

When a high sensitive galvanometer is required, move short circuiting bar and short "INT.GA." terminals.

After that, connect the galvanometer to "EXT. GA." terminals are shown in Fig. 3.2.

### 3.3 External Power Supply

When external power supply is necessary, connect the power supply to  $-B$  and  $+B$  terminals and turn the power supply selector switch to "EXT BA".

Minimum circuit resistance between  $-B$  and  $+B$  terminals is approximate 1010 ohms.

Maximum external power supply voltage is 70V DC and maximum current is 60mA DC (Continuous).

1 K $\Omega$  (2W type) protective resistance is inserted between the external power supply and bridges, so when the  $\times 1000$  dial is set to 0, the circuit is protected from overcurrent.

### 3.4 Cell Replacement

Remove the cell cover on the bottom of the case, by pulling leg of the cover while pushing the clamping plate towards the arrowed direction to the end. To restore the cell cover, push the clamping plate towards the arrowed direction, insert the hollowed part of the cover under the clamping plate and press the cover down.




Fig 3.4 Removal of Cell Cover




Fig 3.5 Bottom View

## 4. OPERATION

### 4.1 Preparation

- (1) Confirm that EXT. GA terminals are perfectly short-circuited with short circuiting bar.
- (2) Confirm that the galvanometer indicates "0" by opening Rx terminals without pushing GA and BA button switch.  
If the galvanometer does not indicate "0", adjust the zero point by turning the zero adjustor. Depress BA push button switch.
- (3) GA button switch should be at OFF position.

### 4.2 Resistance Measurement

- (1) Apply unknown resistor to Rx terminals.
- (2) Turn the selector switch to "R"
- (3) Set the MULTIPLY dial to proper range according to Table 4.1.
- (4) Set the Measuring dial at 1999 and push BA push button switch. Then push GA push button switch for a moment to check to which direction, +or -, the galvanometer deflects.

(5) When the pointer deflects + side, increase measuring dials, and when the pointer deflects –(minus) side, decrease measuring dials.


Adjust measuring dials until the galvanometer indicates "0".

Then, the unknown resistance value is measured by the following equation.

Rx	MULTIPLY
less than 10Ω	0.001
10Ω to 100Ω	0.01
100Ω to 1kΩ	0.1
1kΩ to 10kΩ	1
10kΩ to 100kΩ	10
100kΩ to 1 MΩ	100
1MΩ to 10MΩ	1000

**Table 4.1 MULTIPLY Dial Setting**

$$R_x = (\text{MULTIPLY factor}) \times (\text{Total value of MEASURING DIALS}) \text{ [ohms]}$$



**Fig 4.1 Resistance Measurement**

### 4.3 To find out approximate value of Rx

When the resistance value to be measured is entirely unknown and if there is no suitable circuit tester (ohm meter) available, the following procedure shall be effected to find out approximate value of the unknown resistance.



- (1) Connect the looped line under test to Rx terminals. Connect "G" terminal to the earth.
- (2) Turn the selector switch to "MV".
- (3) Set MULTIPLY dial between M10, M100 and M1000.
- (4) Press the "BA" button switch and "GA" button switch. Adjust measuring arm dials until the galvanometer indicates "0".
- (5) Obtain the value referring to the following equation:


$$R_{x1} = 2L \cdot \frac{\text{(MULTIPLY factor)}}{\text{(MULTIPLY factor)} + \text{(Total value)}}$$

of MEASURING DIALS) ohms

- $R_{x1}$ : Resistance between  $\times 1$  terminal and the fault point.
- $2L$ : Total resistance of looped line under test.

## 4.6 Varley Loop Test

Simplified circuit diagram of Varley loop test is illustrated in Fig. 4.3.



**Table 4.3 Varley Loop Test**

- (1) Connect the looped line under test to Rx terminals. Connect the "G" terminal to the earth.
- (2) Turn the selector switch to "MV".
- (3) Set the MULTIPLY dial to proper range of 0.001 to 1000.

- (4) Press the "BA" button switch and "GA" button switch. Adjust measuring arm dials until the galvanometer indicates "0".
- (5) Obtain the value referring to the following equation:

$$R_{x2} = \frac{2L - (\text{MULTIPLY factor}) \times (\text{Total value of MEASURING DIALS})}{1 + (\text{MULTIPLY factor})} \text{ ohms}$$

$R_{x2}$ : Resistance between  $X_2$  terminal and the fault point.

$2L$ : Total resistance of looped line under test.

## 5. PRINCIPLES OF OPERATION

Fig.5.1 is the theoretical diagram of Wheatstone bridge. When the current at the galvanometer is set to zero by adjusting  $R_s$ , the following equation will be established.

$$I_x \cdot R_A = I_s \cdot R_B$$

$$I_x \cdot R_x = I_s \cdot R_s$$

$$\frac{I_s}{I_x} = \frac{R_x}{R_s} = \frac{R_A}{R_B}$$

$$R_x = \frac{R_A}{R_B} R_s$$

As this 2755 Portable Wheatstone Bridge is so designed that  $R_A/R_B$  can be set within the range of 0.001 to 1000 by MULTIPLY dial, the unknown resistance value  $R_x$  can be obtained by multiplying the  $R_s$  value by the multiplying factor.




Fig.5.1 Theoretical Circuit Diagram

## 6. MAINTENANCE




Fig.6.1 Component Location Diagram

PART LIST

R1	Resistor, Manganin wire wounded	1Ω	R23	"	8.902Ω
R2	"	2Ω	R24	"	0.999Ω
R3	"	"	R25	"	111.1Ω
R4	"	5Ω	R26	"	10.1Ω
R5	"	10Ω	R27	Resistor, Carbon film	RD1/4PY 330ΩJ
R6	"	20Ω	R28	"	RD2PY 10ΩJ
R7	"	"	R29	"	RD2PY 510ΩJ
R8	"	50Ω	R30	"	RD2PY 510ΩJ
R9	"	100Ω	D1	Diode, Silicon	10D4 or equivalent
R10	"	200Ω	D2	"	"
R11	"	"	GA	Galvanometer, Moving coil type	B9350DM
R12	"	500Ω	K1	Switch, Push button	A9150YB
R13	"	1000Ω	K2	"	"
R14	"	2000Ω	S1	Switch, Rotary	B9350BP
R15	"	"	S2	"	"
R16	"	5000Ω	S3	"	B9350BP
R17	"	0.999Ω	S4	"	"
R18	"	8.902Ω	S5	"	A9285SR
R19	"	81.009Ω	S6	Switch, Toggle	A9042SS
R20	"	409.09Ω	S7	Switch, Toggle	"
R21	"	409.09Ω	BA	Dry cell (three)	Type SUM-1
R22	"	81.009Ω		Circuit Board	B9350DQ




Fig.6.2 Circuit Diagram



Yokogawa Meters & Instruments Corporation

---

**Yokogawa Meters & Instruments Corporation**

**International Sales Dept.**

Tachihi Bld. No.2, 6-1-3, Sakaecho, Tachikawa-shi, Tokyo 190-8586 Japan  
Phone: 81-42-534-1413, Facsimile: 81-42-534-1426

**YOKOGAWA CORPORATION OF AMERICA (U.S.A.)**

Phone: 1-770-253-7000 Facsimile: 1-770-251-2088

**YOKOGAWA EUROPE B. V. (THE NETHERLANDS)**

Phone: 31-334-64-1611 Facsimile: 31-334-64-1610

**YOKOGAWA ENGINEERING ASIA PTE. LTD. (SINGAPORE)**

Phone: 65-6241-9933 Facsimile: 65-6241-2606

**YOKOGAWA AMERICA DO SUL S. A. (BRAZIL)**

Phone: 55-11-5681-2400 Facsimile: 55-11-5681-1274

**YOKOGAWA MEASURING INSTRUMENTS KOREA CORPORATION (KOREA)**

Phone: 82-2-551-0660 to -0664 Facsimile: 82-2-551-0665

**YOKOGAWA AUSTRALIA PTY. LTD. (AUSTRALIA)**

Phone: 61-2-9805-0699 Facsimile: 61-2-9888-1844

**YOKOGAWA INDIA LTD. (INDIA)**

Phone: 91-80-4158-6000 Facsimile: 91-80-2852-1441

**YOKOGAWA SHANGHAI TRADING CO., LTD. (CHINA)**

Phone: 86-21-6880-8107 Facsimile: 86-21-6880-4987

**YOKOGAWA MIDDLE EAST E. C. (BAHRAIN)**

Phone: 973-358100 Facsimile: 973-336100

**LTD. YOKOGAWA ELECTRIC (RUSSIAN FEDERATION)**

Phone: 7-095-737-7868 Facsimile: 7-095-737-7869

---