Digital Multimeter Selection Guide

Model	Type	Max. Value	Display						Measurement Items											Additional Functions								External View
			Dual	Bar Graph	Back-lit	AC RMS	Voltage	AC + DC	Current	AC + DC A	Resistance	Continuity Check	Diode Test	Frequency	Temperature	Capacitance	Communication	Data Memory	Max./Min. Value Memory	Relative Value Computation	Logarithm Computation	Data Hold	Auto Hold	Peak Hold	Overvoltage Input Warning	PC Connection	Auto Power Off	
TY710	Handheld	50000	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●		●	●	●	
TY720			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	
TY520		6000		●	●	●	●		●		●	●	●	●	●	●				●		●	●		●		●	
TY530				●	●	●	●		●		●	●	●	●	●	●	●	●	●	●		●	●		●	●	●	
73201		4300					●		●		●	●	●										●		◎		●	
73202							●		●		●	●	●			●							●		◎		●	
73203							●		●		●	●	●			●							●		◎		●	
73204							●				●	●	●										●		◎		●	
73101	Pocket-sized	4300					●				●	●	●										●				●	

◎ : Also functions as excessive current input warning.